

FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D

FIG. 5A





FIG. 5B

Defects in PLD ZnO films

(790°C)

FIG. 6A



inversion domains



FIG. 6B